

Gilson BROTHERS COMPANY

BOX 152, PLYMOUTH, WISCONSIN 53073, U.S.A., PHONE (414) 893-1011

DATE: October 1, 1979

Service Bulletin #135

TO: All Authorized Service Accounts And Microfiche Holders

SUBJECT: Auger Idler Arm Support Tab Service Kit #89973

MODELS INVOLVED: All 4 H.P., 5 H.P. Units With 18" - 20" - 24"
Width Cut

Corrected to 89473
in S.B. 135a

Requests have been received for a replacement auger idler rod support tab adaptable to the units stated above.

Service Kit #89473 has been established to provide the field with an alternative to major disassembly and/or complete replacement of the auger housing in order to repair the broken support tab (front end of rod).

A slot is cut into the right side of the frame assembly (when viewed from operators position). The new replacement tab is inserted through the slot from the outside, and secured with the same bolt retaining the belt guard.

Flat rate for warranty repairs will be two (2) hours.

GILSON BROTHERS COMPANY

Service Department

RLM/bes

O U T D O O R P O W E R E Q U I P M E N T

PLANTS AT: MISSISSAUGA, ONT., STATESVILLE, N.C., FREDONIA AND PLYMOUTH, WIS.