

Gilson

AMERICA'S BEST BUY

GILSON BROTHERS COMPANY
Post Office Box 152
Plymouth, Wisconsin 53073 U.S.A.
Phone (414) 893-1011 Telex 2-6786

May 24, 1982

Service Bulletin #173

To: All Distributors, Dealers and Microfiche Holders

Subject: Auger Pulley Belt Finger Kit No. 89709
For 5hp-5 Speed Units - Snowthrower

Models: 55204 - 55242 - 09GN5239 (ST524) GIS7506A18 - 35261A

Reports have been received from the field that the auger belt hangs below the V-groove of the large pulley under the engine housing. When the snowthrower is operated on an angle and repeatedly clutched, the belt may not center to the pulley groove.

When this condition exists, it is recommended that a belt finger be added to hold the belt into the larger auger pulley V-groove.

Part Kit No. 89709 may be ordered and installed under warranty if the problem occurs within the warranty period. The approximate installation time is 20 minutes.

Service Department

RLM:bb